

1/2

A ROTARY KILN WITH A HOLLOW BRICK INSULATING LINING

Ricardo A. Mosci




Fig. 1




Fig. 2




Fig. 3